

WonderWink[®] Men's Premiere Flex $^{\text{TM}}$ V-Neck Top WW5068



- 78/20/2 poly/rayon/spandex
- V-neckline
- Shoulder badge loop
- Left chest pocket with pen slot
- Top-loading front pockets with interior right pocket
- Side vents
- WonderWink heat transfer logo at left chest pocket
- Modern fit

CARE INSTRUCTIONS


Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.



front



HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SIZE CHART

	XS	S	М	L	XL	2XL	3XL	4XL	5XL
Chest	33-35	36-38	39-41	42-44	45-48	49-52	53-56	57-60	61-64

COLOR INFORMATION



Black PMS PROCESS BLACK C



Nav



Navy PMS 654C



Pewter PMS 432C



Royal PMS 2145C



Teal Blue



White PMS WHITE



PMS 222C